



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way

Wooster, Ohio 44691

Toll Free: **1-800-421-5141**

Phone: 330-264-3299

Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West

Conroe, Texas 77304

Phone: **1-888-987-4267**

Phone: 1-936-273-2661

Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.

Plymouth, MI 48170

Toll Free: **1-800-421-5141**

Phone: 734-454-3485

Fax: 734-454-7110

We **STRONGLY** urge corrosion testing!
Click here for corrosion coupons or a **FREE** corrosion consultation!

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended

PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Abletic acid	X	X		X	X	X	X
Acetanilide	X	X		X	X	X	X
Acetic acid	X	X	XX	XX	XXX	XX	XX
Acetic aldehyde	X	X		X	X	X	X
Acetoncyanhydrine	X	X		X	X	X	
Acetone	X	X		X	X	X	X
Acetophenetidine	X	X		X	X	X	X
Acetophenone	X	X		X	X	X	X
Acetylacetone	X	X		X	X		
Acetylchloride	X	X	XXX	X	X	X	XX
Acetylene (Cu < 65%)	X	X		X	X	X	X
Acetylsalicylic acid	X	X		X	X	X	X
Acridine	X			X			X
Acroleine	X	X		X	XX	XX	X
Acrylonitrile	X	X		X	X	X	X
Adipic acid	X	X		X	X	X	X
Aktivin (chloramines T)							X
Alizarine	X			X	X	X	X
Allyl amine	X						X
Allyl chloride	X			X	X	X	X
Allyl sulphide							X
Allylic alcohol	X	X		X	X	X	X
Aluminium acetate	X	XX		XX	XX	XX	XX
Aluminium alkyle				X	X	X	X
Aluminium chlorate	X		X	X	X	X	X
Aluminium chloride	X	XX	X	X	XX	XX	XXX
Aluminium ethylate	X			X	X	X	X
Aluminium fluoride		XXX	XXX	X	X	X	
Aluminium formiate	X	X		X	X	X	X
Aluminium nitrate		X		X	X	X	X
Aluminium hydroxide	XXX	XX	XX	XX	XX	XX	XX
Aluminium silicofluoride				X	X	X	X
Aluminium sulphate	X	X		X	XXX	XXX	XX
Amines and amination	X			X	X	X	X
2-aminoanthrachinone				X	X	X	X
p-aminobenzene	X			X	XX		
m-aminobenzenesulfonic acid	X			X	X	X	X
p-aminobenzenesulfonic acid	X			X	X	X	X
Aminobenzoic acid	X	X		X	X	X	X
5-amino-2-oxybenzoic acid	X			X	X	X	X
m-aminophenole	X			X	X	X	X
2-aminopyridine				X	X	X	X
p-aminosalicylic acid	X			X	X	X	X
hydroxide	XX	X		X	XX	XX	X



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way

Wooster, Ohio 44691

Toll Free: **1-800-421-5141**

Phone: 330-264-3299

Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West

Conroe, Texas 77304

Phone: **1-888-987-4267**

Phone: 1-936-273-2661

Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.

Plymouth, MI 48170

Toll Free: **1-800-421-5141**

Phone: 734-454-3485

Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Ammonium acetate				X	X	X	X
Ammonium bicarbonate	X			XXX	XX	XXX	XX
Ammonium bromide	X			X	X	X	X
Ammonium carbonate	X			XX	XXX	XX	XX
Ammonium chloride	XX	X		XXX	XXX	XX	XXX
Ammonium citrate	X	X		X	X	X	X
Ammonium difluoride					XX	XX	X
Ammonium diphosphate	X	X		X	X	X	X
Ammonium disulfite	X			X	X	X	X
Ammonium fluoride					XX	XX	XX
Ammonium fluorsilicate				X	X	X	X
Ammonium formate	X	X		X	X	X	X
Ammonium molybdate		X					X
Ammonium monophosphate	X			X	X	X	X
Ammonium nitrate	X	X		XX	XXX	XXX	X
Ammonium oxalate	X			XX	XXX	XXX	XX
Ammonium perchlorate	X			X			X
Ammonium persulphate	X			XX	XXX	XXX	XX
Ammonium phosphate	X			XX	XX	XX	XX
Ammonium picrate				X	X	X	X
Ammonium rhodanide				X	X	X	X
Ammonium sulphamate	X	X		X	X	X	X
Ammonium sulphate	X	X		XX	XXX	XXX	XXX
Ammonium sulfite	X			XX	XXX	XXX	XX
Ammonium tungstate					XXX	XXX	X
Amyl acetate	X	X		X	X	X	X
Amyl alcohol	X	X		X	X	X	X
Amyl amine				X	X	X	X
Amyl chloride	X			X	X	XX	XX
Amyl mercaptane				X	X	X	X
Amyl nitrate							X
p-amyI phenole	X	X		X	X	X	X
Amyl propionate	X	X		X	X	X	X
Aniline	X	X		XX	XXX	XXX	XX
Aniline hydrochloride	X		X	X	XXX	XXX	XXX
Anis aldehyde	X	X		X	X	X	X
Anisidine	X			X	X	X	X
Anis oil	X	X		X	X	X	X
Anisol	X	X		X	X	X	X
Antimony chloride	X			X	X	X	XXX
Apple juice -pulp	X				X	X	X
Aqua regia	X	X	XXX	XXX	XXX	XXX	XXX
Arachic acid	X			X	X	X	X
Aralene	X	X		X	X	X	X
Argon	X	X		X	X	X	X
Arsenic					XX		X
Arsenic acid, pentoxide	X			XX	XXX	XXX	XX
Arsenous acids	X			X	X	X	X
Arsenic trioxide				X	X	X	X
Aspartic acid	X			X			X
Asphalt				X	X	X	X
Atmosphere (air)	X	X		X	X	X	X
Azobenzene	X	X		X	X	X	X



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way
 Wooster, Ohio 44691
 Toll Free: **1-800-421-5141**
 Phone: 330-264-3299
 Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West
 Conroe, Texas 77304
 Phone: **1-888-987-4267**
 Phone: 1-936-273-2661
 Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.
 Plymouth, MI 48170
 Toll Free: **1-800-421-5141**
 Phone: 734-454-3485
 Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Bacitracine				X			X
Baking powder	X	X		X	X	X	X
Barium carbonate	X			XX		XX	XXX
Barium chlorate	X			X	X	X	X
Barium chloride	X	X	XX	X	XX	XX	XX
Barium cyanide	XXX				X	XXX	X
Barium hydroxide	XXX			XX	X	XX	X
Barium nitrate	X			XX	XX	XX	X
Barium oxide				X		X	X
Barium peroxide	XXX				XX	XX	XX
Barium sulphate	X	X		XX	XX	XX	XX
Barium (poly)-sulphide	XXX				XX	X	XX
Beer	X	X		X	X	X	X
Bees Wax	X	X		X	X	X	X
Beer Wort	X	X		X	X	X	X
Benzaldehyde	X			X	XX	XX	X
Benzamide	X	X		X	X	X	X
Benzanthrene	X			X	X	X	X
Benzine	X	X		X	X	X	X
Benzene	X	X		XX	X	X	XX
Benzene peroxide				X	X	X	X
Benzene-sulfonic acid	X			X	XX	X	X
Benzidine	X	X		X	X	X	X
Benzidine(-3-sulfonic acid)	X	X		X	X	X	X
Benzile	X	X		X	X	X	X
Benzilic acid				X	X	X	X
Benzoic acid	X	X		X	X	XX	XX
Benzoic acid anhydride				X	X	X	X
Benzoic acid sulfamide	X			X	X	X	X
Benzoine				X	X	X	X
Benzonitrile	X	X		X	X	X	X
1,4-benzoquinone				X	X	X	X
Benzotrithloride				X	X	X	
Benzotrifluoride				X	X	X	X
Benzychloride	X			X	XX	XX	
Benzy acetate	X			X	X	X	X
Benzy alcohol	X			X	X	X	X
Benzy amine	X			X	X	X	X
Benzy benzoate	X			X	X	X	X
Benzy chloride	X			X	X	X	X
Benzy phenol	X			X	X	X	X
Benzy salicylate	X	X		X	X	X	X
Beryllium chloride	X			X	XX	XX	XX
Beryllium fluoride	X			X	X	X	X
Beryllium sulphate	X			X	X	X	X
Blood	X	X		X	X	X	X
Borax							X
Boric acid	XX	X		X	XX	XX	XX
Borneol	X	X		X	X	X	X
Bornyl acetate	X			X	X	X	X
Bornyl chloride	X			X	X	X	X
Bornyl formate	X			X	X	X	X
Boron phosphate				XXX	XXX	XXX	
Boron trifluoride						X	X
Brackish water					XX	XX	
Brake fluids	X	X		X	X	X	X



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way

Wooster, Ohio 44691

Toll Free: **1-800-421-5141**

Phone: 330-264-3299

Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West

Conroe, Texas 77304

Phone: **1-888-987-4267**

Phone: 1-936-273-2661

Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.

Plymouth, MI 48170

Toll Free: **1-800-421-5141**

Phone: 734-454-3485

Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Brandy							X
Bromic acid					XXX	XXX	XXX
Bromine	X	XXX	XXX	XXX	XXX	XXX	XXX
Bromine trifluoride	XXX	XXX	XXX		X	X	X
Bromobenzene	X	X		X	X	X	X
Bromoform	X			X	X	X	X
1,3-butadiene							X
Butane				X	X	X	X
Butane diol	X			X	X	X	X
Butter	X	X					X
Buttermilk	X				XX	XX	X
Butyl acetate	X	X		X	XX	XX	XX
Butyl alcohol	X	X		X	X	X	X
Butylamine				X	X	X	X
Butyl benzoate				X	X	X	X
Butyl butyrate	X			X	X	X	X
Butyl chloride	X			X	X	X	XX
Butylene	X			X	X	X	X
n-butyl ether	X			X	X	X	X
n-butyl glycol	X			X	X	X	X
Butyl mercaptane				X	X		
Butyl phenol (tertiary)				X	X	X	X
Butyl phthalate	X			X	X	X	X
Butyl stearate	X	X		X	X	X	X
Butyric acid	X			X	XXX	XXX	XX
Cadmium chloride	X		X	X	XX		X
Cadmium cyanide					XXX		
Cadmium sulphate	X			X	X	X	X
Caffeine	X	X		X	X	X	X
Calcium							X
Calcium acetate	X	X		X	X	X	X
Calcium arsenate							X
Calcium benzoate	X	X		X	X	X	X
Calcium bisulphate	X	X		X	XXX	XXX	X
Calcium bromide	X	X	X	X	XX	XX	XX
Calcium carbonate	X	X		XX	XX	XX	X
Calcium chlorate		X		X	XX	X	X
Calcium chloride	X	X	X	X	XX	XX	XX
Calcium chromate				X	X	X	X
Calcium fluoride	XXX		X	X	X	X	X
Calcium gluconate	X	X		X	X	X	X
Calcium hydride				X	X	X	X
Calcium hydroxide	X			XX	XXX	XXX	XXX
Calcium hypochloride	X	X	XX	XX	XXX	XXX	XXX
Calcium lactate	X	X		X	X	X	X
Calcium nitrate	X			X	XX	X	XX
Calcium oxalate	X			X	X	X	X
Calcium oxide				X	X	X	X
Calcium permanganate		X		X	X	X	X
Calcium peroxide							X
Calcium phosphate	X	X		X	X	X	X
Calcium rhodanide				X	X	X	XX
Calcium stearate	X	X		X	X	X	X
Calcium sulphate	X	X		XX	XX	XX	XX
Calcium sulphide					XX		X
Calcium sulphite	X	X			XX	XX	X
Calcium tungstate				X	X	X	X
Camphene	X	X		X	X	X	X
Camphor							X



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way
 Wooster, Ohio 44691
 Toll Free: **1-800-421-5141**
 Phone: 330-264-3299
 Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West
 Conroe, Texas 77304
 Phone: **1-888-987-4267**
 Phone: 1-936-273-2661
 Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.
 Plymouth, MI 48170
 Toll Free: **1-800-421-5141**
 Phone: 734-454-3485
 Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Camphor	X	X		X	X	X	X
Camphoric acid	X	X		X	X	X	X
l-camphor sulfonic acid	X			X	XX	XX	XX
n-capric acid	X	X		X	XX	XX	X
E-caprolactame				X	X	X	X
Caproic acid	X	X		X	XX	XX	X
Caproic aldehyde	X	X		X	X	X	X
Caprylic acid	X			X	XX	X	X
Caprylic alcohol	X	X		X	X	X	X
Capsaicin				X	X	X	X
Carbazole	X	X		X	X	X	X
Carbitol	X	X		X	X	X	X
Carbolic acid	X	X	X	X	XX	XX	XX
Carbolineum	X	X		X	X	X	X
Carbon dioxide	XX	XX		X	XX	XX	X
Carbon monoxide	XX	XX		X	XX	XX	X
Carbon sulfide	X	X		X	X	XX	X
Carbon tetrachloride	X		X	X	X	X	X
Carnallite	X	X		X	X	X	X
Caro acid	X						
Carotene	X	X		X	X	X	X
Cesium chloride				X	X	X	XX
Cesium hydroxide					XX	XX	XX
Cellulose paints	X	X		X	X	X	X
Chloramine				X	X	X	X
Chloramphenicol	X	X					X
Chloranille	X	X			X	X	X
Chlordane				X	X		X
Chloric acid	X				XXX	XXX	XXX
Chlorinated water	X		XX	XX	XXX	XXX	XX
Chlorine	X	XX	XXX	XX	XX	XX	XX
Chlorine dioxide	X			XXX		X	XX
Chlorobenzene	X	X		XX	XX	XX	XX
Chlorobenzotrifluoride				X	X	X	X
Chloroform	X	X		X	X	X	X
Chloronitrobenzenes	X	X		X	X	X	X
Chloronitrobenzoic acid	X	X		X	X	X	X
4-chloro-2-nitrophenol				X	X	X	X
Chlorophenol	X			X	X	X	X
Chlorophenoxyacetic acid	X			X	X	X	X
Chlorophyll	X	X		X	X	X	X
Chloropikrine	X			X	X	X	X
Chloroprene				X	X	X	X
Chlorosulfonic acid	X	X	XX	X	XX	XX	XX
Chlorotoluene	X	X		X	X	X	X
Chlorotrifluoroethylene				X	X	X	X
Chromic acid, oxide	X	X	X	XXX	XXX	XXX	XXX
Chromium chloride	X			X	XX		XX
Chromium fluoride	X					X	
Chromium nitrate		X					X
Chromium oxide, hydroxide	X	X		X	X	X	X
Chromium phosphate	X			X	X	X	X
Chromium sulphate	X			X	XX	XX	XX
Chromyl chloride	X	X		X	X	X	X
Citral	X	X		X	X	X	X
Citric acid	X		XX	X	XXX	XXX	XXX
Citronellal	X	X		X	X	X	X
Citronellol	X	X		X	X	X	X



Corrosion Chart

TITANIUM TANTALUM ZIRCONIUM HASTELLOY® DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way
Wooster, Ohio 44691
Toll Free: **1-800-421-5141**
Phone: 330-264-3299
Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West
Conroe, Texas 77304
Phone: **1-888-987-4267**
Phone: 1-936-273-2661
Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.
Plymouth, MI 48170
Toll Free: **1-800-421-5141**
Phone: 734-454-3485
Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Citrus fruit	X	X		X	XX	XX	X
Citrus oil	X	X		X	X	X	X
City gas	X	X		X	XX	XX	X
Cocaine	X			X	X	X	X
Codein salts	X			X	X	X	XX
Copper acetate	X	X		XX	XX	XX	X
Copper carbonate	X	X		XXX	XX	XX	XXX
Copper chloride	X			XXX	XXX	XXX	XXX
Copper cyanide							X
Copper nitrate	X			XX		XXX	XX
Copper oxide					X	X	
Copper sulphate	X	X		XX	XXX	XXX	XX
Creosote	X			XX		XX	XX
Cresol	X	X		X	X	XX	X
Croton aldehyde	X			X	X	X	X
Crotonic acid	X	X		X	X	X	X
Cumarine	X	X			XX	XXX	X
Cumarone, resin	X	X		X	X	X	X
Cumene	X	X		X	X	X	X
Cyanacetic acid	X	X					XX
Cyan amide		X		X	X	X	X
Cyanogen chloride	X			X	X	X	X
Cyanogen, Dicyanogen	X						X
Cyclohexane	X	X		X	X	X	X
Cyclohexanol	X	X		X	X	X	X
Cyclohexene	X	X		X	X	X	X
Cyclohexylamine					XX	XX	X
Cyclopentane, cyclopentadiene	X	X		X	X	X	X
Cystine	X	X					X
Deuterium oxide		X		X	X	X	X
Dextrine	X	X		X	X	X	X
Dextrose	X	X		X	X	X	X
Dibenzyle	X	X		X	X	X	X
Dibutylphthalate	X	X		X	X	X	X
Dichloroethane					X	X	
Dichloroethylene	X	X		XX	X	X	X
Diethyl amine	XX	X			XX	XX	X
Dimethyl aniline	X	X		X	X	X	X
Dimethyl ether	X	X		X	X	X	X
Dioxane	X	X		X	X	X	X
Diphenyl	X	X		X	X	X	X
Diphenyl amine	X	X		X	X	X	X
Diphenylene oxide	X	X		X	X	X	X
Diphenylketone	X	X		X	X	X	X
DMDT	X	X		X	X	X	X
Ethane	X	X		X	X	X	X
Ethanol	X	X		X	X	X	X
Ethanoamine	X	X					X
Ether	X			XX		XX	XX
Ethyl acetate	X	X		XX	XX	XX	XX
Ethyl benzen	X	X		X	X	X	X
Ethylbutyrate	X	X		X	X	X	X
Ethyl chloride	X	X		X	X	X	X
Ethyl ether	X	X		X	X	X	X
Ethyl lactate	X	X		X	X	X	X
Ethylene	X	X		X	X	X	X
Ethylene bromide	X	X		X	X	X	X
Ethylenechlorhydrine	X	X		X	X	X	X
Ethylene chloride	X	X		X	X	X	X
Ethylene cyanhydrine	X	X		X	X	X	X



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way
 Wooster, Ohio 44691
 Toll Free: **1-800-421-5141**
 Phone: 330-264-3299
 Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West
 Conroe, Texas 77304
 Phone: **1-888-987-4267**
 Phone: 1-936-273-2661
 Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.
 Plymouth, MI 48170
 Toll Free: **1-800-421-5141**
 Phone: 734-454-3485
 Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended

PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Ethylenediamine	X			XX			X
Ethylendichloride	X			XX		XXX	XXX
Ethylenglycol	X			X	XX	XX	XX
Ethyleneimine							X
Ethyl nitrite							X
Ethyleneoxide	X	X		X	X	X	XXX
Ethyl stearate	X	X		X	X	X	X
Ethyl sulphuric acid	X			X			
Extremely pure water	X	X	X	X	X	X	X
Fatty acids	X	X		X	XX	XX	X
Fatty alcohol	X	X		X	X	X	X
Fats and waxes	X	X		X	X	X	X
Ferric chloride	X	X	XXX	XXX	XXX	XXX	XXX
Ferric sulphate	X	X	XX	XXX	XXX	XXX	X
Ferrous chloride	X	X		XX	XXX	XXX	XXX
Ferrous sulphate	X	X		XX	XXX	XXX	XX
Fluoric acid	XXX	XXX	XXX	XX	XX	XX	XXX
Fluorhydrocarbon	XX	XX		X	X	X	X
Fluorine	XXX	XX			XX	XX	XX
Fluorocarbon				X	X	X	XX
Halogen compounds	XX			X	XX	XX	XX
Fluorochlorocarbon				X	X	X	XX
Metalddehyde = formd	X	X		XX	X	X	X
Formamide	X	X		X	XX	X	X
Formic acid	X	X	X	X	XXX	XXX	XX
Furfural	X	X		X	XX	XX	XX
Gallic acid							X
Gelatin	X	X		X	X	X	X
Glacial acetic anhydride					X		
Gluconic acid	X	X		X	X	X	X
Glucose	X			X	X	X	X
Glutamic acid	X	X			XX	X	X
Glycerine	X	X		X	X	X	X
Hemp and jute	X			X	X	X	X
Heptane	X	X		XX	X	X	XX
Hexachloroethane	X			XX	XX	XX	XX
Hydrazine				XX	XXX	XXX	XX
Hydrazine sulphate	X		XX	XX	XXX	XXX	
Hydrobromic acid			XX				X
Hydrochloric acid (<1%)	X	XX	X	XX	XX	XX	XXX
Hydrochloric acid	X	XX	X	XXX	XXX	XXX	XXX
Hydrocyanic acid	X	X		XX	XXX	XXX	XXX
Hydrogen							XX
Hydrogen bromide	X			XX	XX		XXX
Hydrogen iodide, Iodic acid	X	X		X	XX	XX	XX
Hydrogen peroxide	X	XXX	X	XXX	XX	XXX	X
Hydrogen sulphide	X	X			XX		X
Hydroquinone	X	X		X	X	X	X
Impregnating oils	X	X		X	X	X	X
Indol	X	X		X	X	X	X
Iodine	X	XX	XX	XX	XX	XX	XX
Iodoform	X	X		X	X	X	
Iron nitrate	X				XXX	XXX	X
Iron phosphate							X
Isatine, derivates	X	X		X	X	X	X
Kerosene	X			X		X	
Lactic acid	X	X	X	XX	XXX	XXX	XX
Lactose	X	X		X	X	X	X
Lead acetate	X			XX	XX	XX	XX



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way
 Wooster, Ohio 44691
 Toll Free: **1-800-421-5141**
 Phone: 330-264-3299
 Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West
 Conroe, Texas 77304
 Phone: **1-888-987-4267**
 Phone: 1-936-273-2661
 Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.
 Plymouth, MI 48170
 Toll Free: **1-800-421-5141**
 Phone: 734-454-3485
 Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Lead arseniate	X			X	X	X	X
Lead baths (electrolyt.)						X	
Lead bromide				XX			XX
Lead carbonate	X			X	X	X	X
Lead chloride	X			X		X	X
Lead chromate	X			X	X	X	X
Lead dioxide	XX			X	X	X	X
Lead (molten)					XXX	XXX	XX
Lead nitrate	X			X	X	X	X
Lead nitride	X			X	X	X	X
Lead oxide	XX			XX			XX
Lead sulphate				X	X	X	X
Lead sulphide					XXX		XX
Lead tetraacetate				X			X
Lead trinitroresorcinate				X		X	X
Lecithine	X	X		X	X	X	X
Levulic acid	X			X	XX	XX	XX
Lignite tar				X	X	X	X
Lime milk							X
Limonene	X	X		X	X	X	X
Linseed oil					X	X	X
Liqueur							X
Lithium carbonate				X	X	X	X
Lithium chloride	X	XX	XX	X	XX	XX	XX
Lithium hydride					XX		X
Lithium hydroxide					XX	X	X
Lithium (molten)	X				XX	XXX	XX
Lithium sulphate	X	X		X	X	X	X
Litopone					X		X
Lysoform							X
Lysol							X
Magnesium bisulphate	XX	XX		XX	XX	XX	XX
Magnesium carbonate	X	X		X	X	X	X
Magnesium chloride	X	X	X	X	XX	XX	XX
Magnesium fluoride					XX	XX	XX
Magnesium hydroxide	X			XX	X	XX	XX
Magnesium (molten)							XX
Magnesium nitrate	X	X		XXX	XXX	XXX	X
Magnesium oxide	X	XX		X	X	X	X
Magnesium oxychloride	X	X		X	X	X	XX
Magnesium silicofluoride	XXX					XX	X
Magnesium sulfite	X	X		X	X	X	X
Magnesium sulphate	X	X		X	X	X	X
Maleic acid	X	X		X	X	X	X
Malic acid	X	X		X	X	X	X
Malonic acid	X	XX		XX	XX	XX	X
Malt		X		X	X	X	X
Maltose	X	X		X	X	X	X
Manganese dioxide	XX	X			XX	XX	X
Manganese sulphate	X	X		X	X	X	X
Manganese chloride	X	X			XX	XX	XX
Manganous chloride							X
Meat							X
Menthol	X	X		X	X	X	X
Mercaptane	X	X		X	XX	XX	X
Mercury	X	XX		XX	X	XXX	X
Mercury chloride	X		X	XXX	XXX	XXX	XXX
Mercury cyanide					XXX	XXX	X
Mercury nitrate					XXX	XXX	X



Corrosion Chart

TITANIUM TANTALUM ZIRCONIUM HASTELLOY® DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way
 Wooster, Ohio 44691
 Toll Free: **1-800-421-5141**
 Phone: 330-264-3299
 Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West
 Conroe, Texas 77304
 Phone: **1-888-987-4267**
 Phone: 1-936-273-2661
 Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.
 Plymouth, MI 48170
 Toll Free: **1-800-421-5141**
 Phone: 734-454-3485
 Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Mercury salts	X						
Methane	XX	XX		X	XX	X	XX
Methanol	XX	XX	X	X	XX	XX	XX
Methyl acetate	X	X		X	XX	X	XX
Methyl alcohol					X	X	X
Methyl aldehyde							X
Methyl amine		X			XX	XXX	XX
Methyl bromide	X			X	X	X	XX
Methyl chloride	X	X		XX	XX	XX	XX
Methyl formiate		X		X	X	X	X
Methylene chloride	X	X		X	X	X	XX
Morpholine	X			X	X	X	X
Naphtaline	X	X		X	X	X	X
Naphtionic acid	X	X		X	X	X	X
Naphtol	X	X		X	X	X	X
Naphtylamine	X	X					X
Naphtylaminesulfonic acid	X						X
Nickel chloride	X	X	X	XX	XXX	XXX	XXX
Nickel nitrate	X	X		XX	XX	XX	X
Nickel salts							X
Nickel sulphate	X	X		XX	XX	XXX	XX
Nitric acid	X	XX	X	XXX	XXX	XXX	X
Nitric acid, strong conc.			X				XX
Nitrobenzene	X	X		X	X	X	X
Nitrogen	X	X		X	X	X	X
Nitrous acid	X			XXX		XXX	XXX
Novocaine							X
Oak extract	X	X		X	X	X	X
Oleic acid					XX	XX	X
Oleum	XXX	XXX		XXX	XX	XXX	XXX
Oxalic acid	X	XX	X	X	XXX	XX	XX
Ozone	X	X			XX	XX	X
Palm oil acid					X	X	X
Paraffine					X	X	X
Peanut butter				X	X	X	X
Perchloroethylene	X	X		X	X	X	X
Perchloric acid			X				XXX
Petrol, Natural gas	X			X	XX	XX	X
Petroleum							X
Phenol	X	X	XX	X	XX	XX	XX
Phosphoric acid	X	XX	XX	XXX	XXX	XXX	XXX
Phtalic acid	X	X		XX	XX	XX	X
Picric acid	X			XXX	XXX	XXX	XXX
Potassium acetate	X	X		X	X	X	X
Potassium bisulfite	X				XX	XX	X
Potassium bromide	X	X		XX	XXX	XXX	XX
Potassium carbonate	XXX			XX	XX	XX	XX
Potassium chlorate	X	X		XX	XXX	XXX	XX
Potassium chloride	X	XX	X	X	X	X	XX
Palm oil acid					X	X	X
Paraffine					X	X	X
Peanut butter				X	X	X	X
Perchloroethylene	X	X		X	X	X	X
Perchloric acid							XXX
Petrol, Natural gas	X			X	XX	XX	X
Petroleum							X
Phenol	X	X		X	XX	XX	XX
Phosphoric acid	X	XX		XXX	XXX	XXX	XXX
Phosphoric acid anhydride							X



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way

Wooster, Ohio 44691

Toll Free: **1-800-421-5141**

Phone: 330-264-3299

Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West

Conroe, Texas 77304

Phone: **1-888-987-4267**

Phone: 1-936-273-2661

Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.

Plymouth, MI 48170

Toll Free: **1-800-421-5141**

Phone: 734-454-3485

Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good, "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Phtalic acid	X	X		XX	XX	XX	X
Picric acid	X			XXX	XXX	XXX	XXX
Potassium							X
Potassium acetate	X	X		X	X	X	X
Potassium bisulfite	X				XX	XX	X
Potassium bisulphate							XX
Potassium bitartrate							XX
Potassium bromide	X	X		XX	XXX	XXX	XX
Potassium carbonate	XXX			XX	XX	XX	XX
Potassium chlorate	X	X		XX	XXX	XXX	XX
Potassium chloride	X	XX		X	X	X	XX
Potassium nitrate			X				
Silver nitrate			X				
Sodium aluminium fluoride		XX		X	X	X	X
Sodium aluminium sulphate	X			X	XX	XX	XX
Sodium arseniate, arsenite				X	X	X	X
Sodium benzoate	X	X		X	X	X	X
Sodium bicarbonate		X		XX	X	X	X
Sodium bisulfite	X	X		XX	XX	XX	XX
Sodium bisulphate	X	XX	X	XX	XX	XX	XX
Sodium borate	XX	X		X	XX	X	XX
Sodium boron hydride							X
Sodium bromate	X						X
Sodium bromide	X	X		X	X	X	XX
Sodium bromite					X		X
Sodium carbonate	XX	XX	X	X	XX	XX	X
Sodium chlorate	X	X	X	XX	XX	XX	XXX
Sodium chloride	X	X	X	X	XX	XX	XX
Sodium chlorite	XX	X		XXX	XX	XX	XX
Sodium chloroacetate	X				X	X	X
Sodium chromate	X	X		X	X	X	XX
Sodium citrate	X			XXX	XX		X
Sodium cyanate		X			XX		X
Sodium cyanide	XX	XX		XX	XX	XXX	XX
Sodium dichromate	XX	XX		XXX	X	X	
Sodium ethylate					X	X	X
Tetraacetate				X	X	X	X
Sodium fluoroacetate					X	X	X
Sodium fluorophosphates							X
Sodium formate	X		X	X	X	X	X
Sodium glutamate				X	X	X	X
Sodium hydrochloride	XX	XX		XX	XX	XX	XX
Sodium hydrogen sulphide			X	X			X
Sodium hydroxide	XXX	XX	XX	XX	XX	XX	XX
Sodium hypochlorite	XX	XX	XX		XX	XX	XX
Sodium iodide	X	X	X		XX	X	XX
Sodium nitrate	X	X		XX	XX	XX	X
Sodium perborate	X			XX	XX	XX	XX
Sodium perchlorate	XX	XX			X	X	X
Sodium peroxide		XXX	X	XX	XX	XX	XX
Sodium phosphate	X			XX	XX	XX	X
Sodium and potassium alloys	X	XX		X	X	XX	XX
Sodium pyrosulfite						X	X
Sodium salicylate	X			X	X	X	XX
Sodium silicate	X		X	X	X	X	X
Sodium sulfite	X	X		XX	X	XX	XX
Sodium sulphate	X	XX	X	XXX	XX	XXX	XX
Sodium sulphide	XX	X	X	XX	XX	XX	XX
Sodium thiosulphate		X		X	X	X	X



Corrosion Chart

TITANIUM · TANTALUM · ZIRCONIUM · HASTELLOY® · DUPLEX STAINLESS STEEL

www.tricormetals.com

Tricor Metals

Ohio Division

3225 West Old Lincoln Way
 Wooster, Ohio 44691
 Toll Free: **1-800-421-5141**
 Phone: 330-264-3299
 Fax: 330-264-1181

Tricor Metals

Texas Division

3517 North Loop 336 West
 Conroe, Texas 77304
 Phone: **1-888-987-4267**
 Phone: 1-936-273-2661
 Fax: 936-273-2669

Tricor Metals

Michigan Division

44696 Helm St.
 Plymouth, MI 48170
 Toll Free: **1-800-421-5141**
 Phone: 734-454-3485
 Fax: 734-454-7110

"X" = Excellent to Very good resistance, "XX"=Good , "XXX" = Not recommended							
PROCESS FLUID	Tantalum	Titanium	Zirconium	Alloy 276	Nickel 200	Monel 400	SS316
Soft soap, suds							X
Stannic chloride			X				
Stannous chloride	X						XX
Stearic acid					X	X	X
Succinic acid	X	X	X	X	X	X	X
Sugar solution					X	XX	X
Sulfamic Acid			X				
Sulphur	X	X		XX	XX	XX	X
Sulphur, boiling							XX
Sulphur chloride (dry)	X			XX		XXX	XXX
Sulphur dioxide	X	XX		XXX	XX	XX	XX
Sulphuric acid	X	XX	XX	XXX	XXX	XXX	XXX
Sulphurous acid	X		XXX	XX		XXX	XX
Sulphurous chloride	X	XX			X	X	XX
Tannic Acid			X				
Tartaric acid			X		XX	XX	XX
Tetrachloroethane			XX				XX
Tin chloride	X	X		X	XX	XX	XX
Tin, molten, 300 Degrees C							X
Tin, molten, 500 Degrees C							XXX
Toluene					X	X	X
Trichloroacetic acid							XXX
Trichloroethylene	X	XX	XX	X	X	X	XX
Tricresylphosphate				X	X		
Trisodiumphosphate			XX				X
Turpentine					X	X	X
Uranium fluorides	XXX			XX	X	X	
Urea	X	X	X	X	XX	XX	X
Uric acid	X		X	X	X	X	X
Vegetal tar, Charcoal	X			X	X	X	X
Vinyl chloride	X			XX	XX	XX	
Wash oil				X		X	X
Xylene					XX	XX	X
Yeast	X	X		X	X	X	X
Zinc chloride	XX	X	X	X	X	XX	XXX
Zinc sulphate	X			XX		XX	XX

**This chart is intended to be used only as guide and provides only overall comparison of the corrosion resistance of the metals/alloys in the chemicals noted. Service conditions (concentrations, temperatures, tramp chemical contaminants, etc) can vary greatly. We strongly urge corrosion testing under anticipated operating conditions. Contact us for corrosion coupons. Tricor Metals assumes no responsibility for the data contained nor for any corrosion issues that arise due to use of this information.